## **Under Review Notification**

Raised By: Vanessa Morel Product #: KSTFP DP TRI-ROLLER FOR BACB10FP BEARINGS

**Date:** 2019.10.30 **Product Name:** KSTFP##-SL SERIES DP TRI-ROLLER SLEEVE

		"Y" or "N" Required for Each Part							t		
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
KSTFP DP	KSTFP DP Rev	Υ	Υ	Ν	Υ	Υ	Ν	N	Ν	19-1115	See below

## Description of Issue:

Issues stated on ADR (Incomplete drawing, Fit issues, manufacturing issues)

KSTFP DP TRI-ROLLER FOR BACB10FP BEARINGS with sleave and all sub assy and parts must be put on HOLD in Plex

KSTFP DP TRI-ROLLER FOR BACB10FP BEARINGS with sleave Finish good stock can be use as is

All sub assy and parts stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must **NOT** be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

**Distribution:** VP Operations Director of Engineering Customer Support Manager Technical Support

Director of Operations Chief Engineer Production Engineers Product Manager - Solutions Provider

Director Quality Assurance Engineering Project Managers Production Planners Supply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene